

**QUESTIONS AND RESPONSES
FOR
REHABILITATE WELL INSIDE BUILDING 3226
AT
EIELSON AIR FORCE BASE, ALASKA**

Solicitation Number: FA5004-09-T-C005

It shall be noted to all interested parties that the following questions have been received in writing regarding the subject acquisition. Additionally, responses have been provided to the below listed questions.

As a reminder, it is the responsibility of all Interested Parties to review this website (<http://www.fedbizopps.gov>) frequently for any updates and/or amendments to any and all subject documents.

Question:

1) I understand that Bid Item No. 0001 is to cover all of the work included in the Statement of Work and, basically, this is reconditioning the existing equipment, if possible, even though the title is a little misleading in that it states "Replace Well Pump".

Response:

CLIN 0001 is to rehabilitate the well pump with all labor to pull the works, redevelop, clean screen, and reinstall the works with rehabilitated pump and motor.

Question:

2) The intent of items 0002, 0003 and 0004 is to provide alternate pricing in the event that the equipment needs to be replaced. That is the way item 0002 is clearly worded. However, 0003 and 0004 state "refurbish" which is not the same as replace or provide new equipment. Please clarify.

Response:

The CLINS are for the refurbishment of the pump and motor and they do not include replacement.